03500.016001.



Cofe \$

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: Sikha Roy
TOMOYA OHNISHI)	•
	:	Group Art Unit: 2879
Appl. No.: 10/002,291)	-
	:	
Filed: December 5, 2001)	
	:	
For: IMAGE DISPLAY APPARATUS)	
HAVING A POTENTIAL	:	
REGULATING ELECTRODE,)	
AN ANODE, AND A SPACING	:	
MEMBER, FOR SUPPRESSING)	
UNDESIRED DISCHARGE	:	
)	
U.S. Patent No.: US 6,803,717 B2	:	
)	
	:	
Issued: October 12, 2004)	September 16, 2005
·		

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Certificate

SEP 2 6 2005

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

of Correction

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Frank A. DeLucia

Attorney for Patentee Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_MAIN 513741v1

PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :

TOMOYA OHNISHI

Page 1 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 24, "inventors" should read --inventor--;

Line 25, "have" should read --has--;

Line 29, "inventors have" should read --inventor has--; and

Line 32, "inventors have" should read --inventor has--.

COLUMN 2

Line 53, "inventors" should read --inventor--.

COLUMN 3

Line 42, "may-preferably" should read --may preferably--, and

"include" should read --includes--

Line 54, "referred" should read --referred to--; and

Line 56, "(hereupon" should read --(hereinafter,--.

COLUMN 4

Line 52, "Hereupon," should read --Hereinafter,--.

COLUMN 6

Line 45, "an" should read --a--.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,803,717 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_MAIN 513741v1

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :

TOMOYA OHNISHI

Page 2 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7

Line 4, "membrane is" should read --membrane--; and Line 24, "an" should read --a--.

COLUMN 8

Line 32, "referred" should read --referred to--; and Line 36, "fist" should read --first--.

COLUMN 9

Line 21, "ordinary" should read --ordinarily--.

COLUMN 10

Line 54, "is" should read --are--; and Line 56, "electrode" should read --electrodes--.

COLUMN 11

Line 58, "inventors" should read --inventor--; and Line 61, "inventors" should read --inventor--.

COLUMN 12

Line 1, "inventors" should read --inventor--; Line 7, "inventors" should read --inventor--; and Line 10, "inventors" should read --inventor--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies @ 30¢ per page

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :

TOMOYA OHNISHI

Page 3 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13

Line 37, "a" should read --an--.

COLUMN 15

Line 11, "limited" should read --limited to--; and Line 58, "(hereupon" should read --(hereinafter,--.

COLUMN 17

Line 8, "rage" should read --range--.

COLUMN 19

Line 36, "inventors" should read --inventor--; Line 42, "inventors" should read --inventor--; and Line 45, "inventors" should read --inventor--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,803,717 B2</u>

No. of add'l. copies @ 30¢ per page

SEP 27 25



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :

TOMOYA OHNISHI

Page 4 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20

Line 23, "plate" should read --paste--;

Line 36, "inventors" should read --inventor--;

Line 39, "inventors" should read --inventor--;

Line 43, "inventors" should read --inventor--;

Line 44, "potions" should read --portions--;

Line 45, "inventors" should read --inventor--;

Line 47, "inventors" should read --inventor--;

Line 52, "inventors" should read --inventor--;

Line 54, "inventors" should read --inventor--; and

Line 60, "inventors" should read --inventor--;

COLUMN 21

Line 64, "inventors" should read --inventor--; and

Line 67, "inventors" should read --inventor--.

COLUMN 22

Line 6, "inventors" should read --inventor--;

Line 11, "inventors" should read --inventor--; and

Line 14, "inventors" should read --inventor--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,803,717 B2</u>

No. of add'l. copies @ 30¢ per page



SEP 27 2

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :

TOMOYA OHNISHI

Page 5 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23

Line 18, "inventors" should read --inventor--;

Line 21, "inventors" should read --inventor--;

Line 29, "inventors" should read --inventor--; and

Line 35, "inventors" should read --inventor--.

COLUMN 24

Line 18, "inventors" should read --inventor--;

Line 24, "inventors" should read --inventor--;

Line 28, "inventors" should read --inventor--;

Line 32, "inventors" should read --inventor--; and

Line 62, "surely" should read --surely be--.

COLUMN 26

Line 5, " (Ω/\Box) ," should read -- (Ω/\Box) ,--; and

Line 47, "eve" should read --even--.

COLUMN 27

Line 40, "than" should read --other than--.

COLUMN 28

Line 43, " 10^4 (Ω/\Box)." should read -- 10^{14} (Ω/\Box).--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY MAIN 513741v1 PATENT NO. US 6,803,717 B2



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :


TOMOYA OHNISHI

Page 6 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 2

Figure 2, should read



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_MAIN 513741v1

PATENT NO. <u>US 6,803,717 B2</u>



Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :

TOMOYA OHNISHI


Page 7 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 8

Figure 11, should read

FIG. 11 PRIOR ART



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,803,717 B2</u>

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :


TOMOYA OHNISHI

Page 8 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 9

Figure 12, should read



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,803,717 B2</u>

No. of add'l. copies @ 30¢ per page



Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :


TOMOYA OHNISHI

Page 9 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 10

Figure 13, should read



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,803,717 B2</u>

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :

TOMOYA OHNISHI

Page 1 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 24, "inventors" should read --inventor--;

Line 25, "have" should read --has--;

Line 29, "inventors have" should read --inventor has--; and

Line 32, "inventors have" should read --inventor has--.

COLUMN 2

Line 53, "inventors" should read --inventor--.

COLUMN 3

Line 42, "may-preferably" should read --may preferably--, and

"include" should read --includes--

Line 54, "referred" should read --referred to--; and

Line 56, "(hereupon" should read --(hereinafter,--.

COLUMN 4

Line 52, "Hereupon," should read --Hereinafter,--.

COLUMN 6

Line 45, "an" should read --a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_MAIN 513741v1 PATENT NO. <u>US 6,803,717 B2</u>



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :

TOMOYA OHNISHI

Page 2 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7

Line 4, "membrane is" should read --membrane--; and Line 24, "an" should read --a--.

COLUMN 8

Line 32, "referred" should read --referred to--; and Line 36, "fist" should read --first--.

COLUMN 9

Line 21, "ordinary" should read --ordinarily--.

COLUMN 10

Line 54, "is" should read --are--; and Line 56, "electrode" should read --electrodes--.

COLUMN 11

Line 58, "inventors" should read --inventor--; and Line 61, "inventors" should read --inventor--.

COLUMN 12

Line 1, "inventors" should read --inventor--; Line 7, "inventors" should read --inventor--; and Line 10, "inventors" should read --inventor--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :

TOMOYA OHNISHI

Page 3 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13

Line 37, "a" should read --an--.

COLUMN 15

Line 11, "limited" should read --limited to--; and Line 58, "(hereupon" should read --(hereinafter,--.

COLUMN 17

Line 8, "rage" should read --range--.

COLUMN 19

Line 36, "inventors" should read --inventor--; Line 42, "inventors" should read --inventor--; and Line 45, "inventors" should read --inventor--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies @ 30¢ per page



een 9.7 190

Stable Here Ould Hill Rish TRIN LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :

TOMOYA OHNISHI

Page 4 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20

Line 23, "plate" should read --paste--;

Line 36, "inventors" should read --inventor--;

Line 39, "inventors" should read --inventor--;

Line 43, "inventors" should read --inventor--;

Line 44, "potions" should read --portions--;

Line 45, "inventors" should read --inventor--;

Line 47, "inventors" should read --inventor--;

Line 52, "inventors" should read --inventor--;

Line 54, "inventors" should read --inventor--; and

Line 60, "inventors" should read --inventor--;

COLUMN 21

Line 64, "inventors" should read --inventor--; and

Line 67, "inventors" should read --inventor--.

COLUMN 22

Line 6, "inventors" should read --inventor--;

Line 11, "inventors" should read --inventor--; and

Line 14, "inventors" should read --inventor--.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,803,717 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :

TOMOYA OHNISHI

Page 5 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23

Line 18, "inventors" should read --inventor--;

Line 21, "inventors" should read --inventor--;

Line 29, "inventors" should read --inventor--; and

Line 35, "inventors" should read --inventor--.

COLUMN 24

Line 18, "inventors" should read --inventor--;

Line 24, "inventors" should read --inventor--;

Line 28, "inventors" should read --inventor--;

Line 32, "inventors" should read --inventor--; and

Line 62, "surely" should read --surely be--.

COLUMN 26

Line 5, " (Ω/\Box) ," should read -- (Ω/\Box) ,--; and

Line 47, "eve" should read --even--.

COLUMN 27

Line 40, "than" should read --other than--.

COLUMN 28

Line 43, " 10^4 (Ω/\square)." should read -- 10^{14} (Ω/\square).--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_MAIN 513741v1

PATENT NO. US 6,803,717 B2



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :


TOMOYA OHNISHI

Page 6 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 2

Figure 2, should read



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,803,717 B2</u>





CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :

TOMOYA OHNISHI


Page 7 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 8

Figure 11, should read

FIG. 11 PRIOR ART



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies @ 30¢ per page



Staple Here Only! PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :


TOMOYA OHNISHI

Page 8 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 9

Figure 12, should read



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_MAIN 513741v1 PATENT NO. <u>US 6,803,717 B2</u>



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,803,717 B2

DATED

October 12, 2004

INVENTOR(S) :


TOMOYA OHNISHI

Page 9 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 10

Figure 13, should read



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,803,717 B2</u>

